


# DETAILED LANDSLIDE AND FLOOD HAZARD MAP OF **4018-I-2 ACLAN QUADRANGLE**





DEPARTMENT OF ENVIRONMENT AND NATURAL RESOURCES **MINES AND GEOSCIENCES BUREAU** North Avenue, Diliman, Quezon City

**Data Sources :** MGB Geohazard Assessment Team Lands Geological Survey Division Geosciences Division MGB Regional Office XIII National Mapping and Resource Information Authority

ALL RIGHTS RESERVED **PUBLISHED DECEMBER 2015**  GIS Processing :

## Coordinate System :

Spheroid :.... Clark 1866 Datum :..... Luzon 1911

Mapping scale 1:10,000

| 1 | I | U | S |  | u | e |
|---|---|---|---|--|---|---|
|   |   |   |   |  |   |   |
|   |   |   |   |  |   |   |

and/or flood duration of less than 1 day. These areas include low hills and gentle slopes. They also have sparse to moderate drainage density.

### Direction of rising floodwater Direction of receding floodwater



 $\overset{1.2}{\otimes}$  Flood depth (meter)

Flashflood exit point