


## DETAILED LANDSLIDE AND FLOOD HAZARD MAP OF TAGANA-AN AND SURIGAO CITY (CAPITAL), SURIGAO DEL NORTE, PHILIPPINES 4120-III-2 HIMAMAUG QUADRANGLE



Lands Geological Survey Division

Lands Geological Survey Division

**GIS Processing:** 


Geosciences Division MGB Regional Office XIII

National Mapping and Resource Information Authority

MINES AND GEOSCIENCES BUREAU

North Avenue, Diliman, Quezon City

**ALL RIGHTS RESERVED PUBLISHED DECEMBER 2015** 



rising floodwater

receding floodwater

Direction of

INDEX MAP:

Track; trail

aggravating factor.

Old landslide deposits

Flood

Recent landslide deposits

Very high landslide susceptibility

High landslide susceptibility

Low landslide susceptibility

**Moderate landslide susceptibility** 

Areas usually with steep to very steep slopes and underlain by weak materials. Recent landslides, escarpments and tension

Areas usually with steep to very steep slopes and underlain by weak materials. Areas with numerous old/inactive landslides.

Areas with moderately steep slopes. Soil creep and other indications of possible landslide occurrence are present.

Areas susceptible to ground subsidence/sinkhole development

Gently sloping areas with no identified landslide.

Areas that could be affected by landslide debris.

**Debris flow / Possible accumulation zone** 

cracks are present. Human initiated effects could be an

Landslide


4120-III-7

(Poblacion) Purok/Sitio location (Barangay)

-→->-> Creep

TTTT Tension crack

Riverbank erosion



Spheroid :..... Clark 1866 Projection:.....Transverse Mercator Datum :..... Luzon 1911

Mapping scale 1:10,000