


DAPA, SURIGAO DEL NORTE, PHILIPPINES **4220-III-1 BAGAKAY QUADRANGLE**

126°1'0"E





DEPARTMENT OF ENVIRONMENT AND NATURAL RESOURCES **MINES AND GEOSCIENCES BUREAU** North Avenue, Diliman, Quezon City

ALL RIGHTS RESERVED **PUBLISHED DECEMBER 2015** GIS Processing :

MGB Geohazard Assessment Team Lands Geological Survey Division Geosciences Division MGB Regional Office XIII

National Mapping and Resource Information Authority

Spheroid :.... Clark 1866 Datum :..... Luzon 1911

Mapping scale 1:10,000

moderate drainage density.

Direction of rising floodwater Direction of receding floodwater



 $\overset{1.2}{\otimes}$ Flood depth (meter)

Flashflood exit point